





## **Gold wire**




## **Aluminium wire**






Fracture or chip-out of die (includes cratering)






Lift die metalization or failure within metalization




Nordson
TEST & INSPECTION

Lift of bond from die metalization






Break in wire at the 'neckdown point' of the first bond




Nordson
TEST & INSPECTION

Break in span of the wire




Nordson
TEST & INSPECTION

Break in wire at the 'neckdown point' of the second bond






Lift of bond from substrate / leadframe / post metalization






Lifted substrate / leadframe / post metalization




Nordson
TEST & INSPECTION

Fracture or lift of substrate / leadframe / post






Operator error or wire damaged / missing prior to test






Fracture or chip-out of die (includes cratering)






Lift die metalization or failure within metalization




Nordson
TEST & INSPECTION

Lift of bond from die metalization






Break in wire at the 'neckdown point' of the first bond






Break in span of the wire






Break in wire at the 'neckdown point' of the second bond






Lift of bond from substrate / leadframe / post metalization






Lifted substrate / leadframe / post metalization





Fracture or lift of substrate / leadframe / post



Nordson
TEST & INSPECTION

Operator error or wire damaged / missing prior to test

